

Code: EE6T2

III B.Tech - II Semester – Regular Examinations – May 2017

**ELECTRICAL MACHINE DESIGN
(ELECTRICAL & ELECTRONICS ENGINEERING)**

Duration: 3 hours

Max. Marks: 70

PART – A

Answer *all* the questions. All questions carry equal marks

11x 2 = 22 M

1.

- a) Mention any 2 advantages of increasing number of poles of D.C machines.
- b) Define specific electric loading.
- c) Write the output equation for the 1-phase and 3-phase transformer.
- d) Compare shell type and core type transformers (list any 2).
- e) List any 2 methods for cooling of transformer.
- f) What are the factors to be considered for choosing the type of winding for a core type transformer?
- g) List any 2 factors that get affected while choosing specific electric loading in a induction motors.
- h) Mention any 2 factors that are get affected by the length of air gap in 3-phase induction motor.
- i) What is crawling and cogging?
- j) What are the effects of short circuit ratio on machine performance?

k) What are the factors that effect the selection of armature slots in a synchronous machine?

PART – B

Answer any *THREE* questions. All questions carry equal marks.

3 x 16 = 48 M

2. a) Explain in detail about the design of field systems of DC Machines. 8 M

b) Find the diameter and length of armature for a 8 kW, 4 pole, 1000 rpm, 200V shunt motor. Given: full load efficiency = 0.89; maximum gap flux density = 0.88 Wb/m²; specific electric loading = 30000; field form factor = 0.8. Assume that the maximum efficiency occurs at full load and the field current is 3% of rated current. The pole face is square. 8 M

3. a) Explain about the construction of single phase transformer in detail. 8 M

b) Calculate the active and reactive components of no-load current of 400V, 50 Hz, single phase transformer having the following data: 8 M
Stacking factor=0.9; density= 7.8×10^3 Kg/m³; length of mean flux path= 2.2 m; gross iron section= 10×10^{-3} m²; primary turns=200; joints equivalent to =0.2 mm of air gap. Use the following data:

B_m (Wb/m ²)	0.9	1.0	1.2	1.3	1.4
Mmf (At/m)	130	210	420	660	1300
Iron loss (W/Kg)	0.8	1.3	1.9	2.4	2.9

4. a) Derive an expression for the no. of cooling tubes required to limit the temperature rise in a 3-phase transformer. Design its tank dimensions and show them pictorially.

8 M

- b) Calculate approximate overall dimensions for a 200 kVA, 6600/440 V, 50 Hz, 3 phase core type transformer. The following data may be assumed: EMF per turn = 9V; maximum flux density = 1 Wb/m²; current density = 2 A/mm²; window space factor = 0.3, overall height = overall width; stacking factor = 0.9; Use a 3 stepped core. For a three stepped core: Width of largest stamping = 0.9 d and Net iron area = 0.6 d² where d is the diameter of the circumscribing circle.

8 M

5. a) Explain in detail about the design of rotor slots and rotor bars in squirrel cage induction motor.

8 M

- b) Find the values of diameter and length of stator core of a 8 kW, 220 V, 50 Hz, 4 pole, three phase induction motor for best power factor. Given the specific magnetic loading = 0.35 Wb/m²; specific electric loading = 20000 A/m; efficiency = 0.9; and power factor = 0.86.

8 M

6. a) Explain in detail about the stator design of synchronous machines. 8 M
- b) What are the factors that will get affected while choosing specific electric and specific magnetic loadings in synchronous machines? 8 M