Code: ME5T2

III B.Tech - I Semester - Regular Examinations - November 2014

METAL CUTTING & MACHINE TOOLS (MECHANICAL ENGINEERING)

Duration: 3 hours Marks: 5x14=70

Answer any FIVE questions. All questions carry equal marks

- 1. a) Categorize the three types of chips. What is BUE. 7 M
 - b) Explain the geometry of a single point cutting tool angles.

 7 M
- 2. Describe the constructional features of speed gear box and feed gear box.

 14 M
- 3. a) What are the different types of lathes. 7 M
 - b) Describe the characteristic features of single and multi spindle automatic lathes. 7 M
- 4. a) How the quick return motion is incorporated in a shaping machine.

 7 M

- b) A hydraulic shaper is used for shaping a plane surface of 30X250 mm with a cutting speed of 60 m/min and feed of 0.6mm per stroke. Calculate the machining time and material removal rate if the depth of cut is 3mm. Also calculate the power consumed in the process. 7 M
- 5. Describe the operations performed and working principle of a slotting machine.
- 6. a) Explain the twist drill geometry with the help of neat sketch. 7 M
 - b) Explain about the tool holding and work holding devices in drilling operation.

 7 M
- 7. a) What is a dividing head. Differentiate between simple and compound indexing.

 10 M
 - b) Differentiate upmilling and downmilling.

 4 M
- 8. a) Featurise the characteristics of various abrasive processes.

7 M

b) Classify the grinding machines based on the type of surface produced.

7 M